Drawings


Model EJA510A and EJA530A Absolute and Gauge Pressure Transmitter

DPharp

[Style: S2]

Unit: mm(approx. inch)

◆ With Process Connection code 7




*1: Applied to Model EJA530A with Measurement span code A, B, and C.


♦ For Process Connection code 4



◆ For Process Connection code 8 and 9



Terminal Configuration



Terminal Wiring

SUPPLY +	Power supply and output terminal
CHECK +	External indicator(ammeter) terminal
÷	Ground terminal